SECRET

14-1661

Chief, Supplementary Programs Division

1 July 1954

Chief, Engineering Division, CC

Project Equipment for

25X1

1. The firm of has constructed the following equipment under Task II, Contract RD-35:

25X1

Description	Quantity
3801 relay 3802 Time Generator 3803 Recorder 3804 Playback Butterfly born 50 mc Butterfly born 250 mc	50 OK 9 - Protetype - works. 50 2 weeks 20 1 weeks 10 6
	3801 relay 3802 Time Generator 3803 Recorder 3804 Playback Butterfly born 50 mc

Since several defects exist in Items 2, 3, 4, and 7, and since funds to correct these defects must be spent from Task V, Contract RD-35, your opinion is requested as to whether an operational need exists for the equipment under your FLINT program.

2. An early enswer to the question posed in this memorandum will be appreciated since, if no operational requirement exists, we desire to have the Contractor curtail work on the equipment as soon as possible.

GBG

OC-E/GBG:dl (1 July '54)

Distribution:

OC-E (T.II)

DL

Chrono

. . .

25**X**1

The state of the s	2 14/80 EY 37/68
BOC 36 REV DATE	219 TYPE 2
ONIG COMP 33 OPI	220 20 100
GRIG CLASS PAGES	REV 2010 AUTH: HR 19-2
JUST REAL	